
Bus facilities Amsterdam Airport Schiphol





Bus Facilities Amsterdam Airport Schiphol




Explanation 'Overview bus gates en bus injection points'

Security Conform EU'

Arrival Bus Injection Points (BIP)	Symbol	s bus gates / bus injection points	Total number of bus gates
A01: backup 1 BIP A04		Schengen bus gate	Schengen bus gates: 17
A03: backup 2 BIP A04	L	EU/NEU bus gate	EU/NEU bus gates: 9
A04: Schengen		NEU bus gate, EU not allowed	NEU bus gates: 7
A08: EU + NEU flights with the status 'Security Conform EU' from A/B/D/E aprons		Bus gate with 2 exits	Bus gates with 2 exits: 4
A09: SkyTeam flights with the status 'None Security Conform EU' (backup A15)		BIP (Bus Injection Point)	WIBO bus gates: 7 (D42, E21, G12, G16)
A12: backup A08 and A14		BIP reserve	Total number of BIP's
A14: NEU flights with the status 'Security Conform EU' from G/J/Y aprons	\	Driving direction buses	Main entrances: 6
A15: None SkyTeam with the status 'None Security Conform EU' (backup A09)		Bus gate with sliding door	Backup: 3
A16: Schengen flights with the status 'None			

Bus facilities Amsterdam Airport Schiphol





Arrivals bus@gate

B/C pier bus@gate positions: 6 x cat4 VOP's

- Arrival flights with the status 'None Security Conform EU'
- Arrival flights EU/NEU with the status 'Security Conform EU'

D pier bus@gate positions: 11 x cat4 + 1 x cat7 (D07) VOP's

- Arrival flights with the status 'None Security Conform EU'
- Arrival flights Schengen (D23 D28)

When a flight arrives at a pier gate and the passenger border status not corresponds with the border status of the terminal area, or if the security status does not meet the requirements 'Security conform EU' all passengers are transported by bus to a BIP corresponding the correct status.

At Schiphol, 18 pier gates are adapted to ensure a safe route to the bus.

The procedure concerning these pier gates

Bus@gate facilities:

- Covered stairways (except C06 and D48)
- Additional handrail unto the platform
- Hook on the bridge door
- Security employee for guidance

has been appointed as 'bus@gate':

- Safe walking route to the bus
- Guide lines
- Parking spot for the bus next to the stairs